

The Boeing Company  
P.O. Box 3707  
Seattle, WA 98124-2207

RECEIVED  
AUG 30 2007

Office of Air Waste & Toxics

August 27, 2007  
G-1241-WDE-166

Shawn Blocker  
RCRA Corrective Action, AWT-121  
U.S. Environmental Protection Agency, Region 10  
1200 Sixth Avenue  
Seattle, Washington 98101

Subject: *Characterization of Caulk in Concrete Pavements Interim Measure  
Work Plan* Final Submittal  
Boeing Plant 2, Seattle/Tukwila, Washington  
EPA ID No. WAD 00925 6819  
RCRA Docket No. 1092-01-22-3008(h)

Dear Mr. Blocker:

Please find enclosed four (4) copies (each with a CD attached) of the subject final Work Plan. Note a CD copy will be provided to Mr. Fujita directly.

This document reflects EPA's comments dated August 14, 2007, our August 23 phone conversation on those comments, and Boeing's Section 10.3 letter dated August 24, 2007. The few changes necessary were made to Work Plan Sections 3.5, 4.2, 4.3, 5.1 and 6.0, and SAP Sections 7.0 and 8.0.

Although we will prepare for the associated field work without delay, we would appreciate your written indication of plan approval be sent also without delay to help ensure the work can proceed in favorable weather conditions.

Please contact me with any questions or comments you may have.

Sincerely,

*Will Ernst*

Will Ernst  
Project Coordinator; Environmental Remediation  
M/C 1W-12; 425.891.7724; 206.544.7297 (fax); [william.d.ernst@boeing.com](mailto:william.d.ernst@boeing.com)

Enclosure

cc: Hideo Fujita, Department of Ecology (by email)  
Brad Helland, Department of Ecology (by email, w/o enclosure)  
Rudy Rogers, Boeing (by email for TSCA coordination)

WA 6819  
8/27/07  
10a

FILE COPY

FILE COPY

USEPA RCRA



3017288

